


STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING  
1594 West North Temple - Suite 1210  
Box 145801  
Salt Lake City, Utah 84114-5801  
Telephone: (801) 538-5291  
Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) Jan 1998 To (mo./yr.) Dec 1998
  2. DOGM File Number (Mine No): M /045 /002
  3. Mine Name: Reilly Wendover
  4. Mineral(s) Mined (or permitted to mine): Potash
  5. Type of mine ☒ Surface Mine or ☐ Underground Mine
  6. Legal Description (Location of Lands Affected):  
      1/4,    1/4,    1/4, Section    , Township    , Range      
      1/4,    1/4,    1/4, Section    , Township    , Range      
      1/4,    1/4,    1/4, Section    , Township    , Range
  7. Name of Operator or Company: Reilly Wendover
  8. Permanent Street Address: 2 1/2 Miles East Frontage Road  
City, State, Zip: Wendover, Utah 84083-0580  
Phone: (435) 665-2241
  9. Company Representative (or designated operator):  
Name: Glenn D. Wadsworth  
Title: Plant Manager  
Business Address: P.O. Box 580  
City, State, Zip: Wendover, Utah 84083-0580  
Phone: (435) 665-2241
- ☒ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was there any mine related activity during the past year? Yes ☒ No ☐
2. If no - what was the last year of activity? \_\_\_\_\_
3. If yes - how much ore or mineral was mined? 332,656 st.

4. Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.  
Cleaned and refurbished 55,900 linear feet of channel/dike  
Approximately 124,300 yds<sup>3</sup>
5. How much **additional acreage** was disturbed during the past year? 64.2
6. How much acreage was **reclaimed** during the past year? None
7. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.  
All areas remained active in 1998
8. What is the **total** disturbed acreage of entire project at years end? 64.2 *299.2 per phone call 12-3-99*
9. Briefly summarize any mining and/or reclamation plans for the upcoming year.  
The mine is scheduled to remain operational during 1999. All areas for  
brine collection will continue to be cleaned. All additional areas will  
continue to be utilized for mining.  
Pond system VI will continue to under construction. (see map)

**NOTE:** Section III., "Additional Information" applies only to **large mining operations**.

III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.


Name (Typed or Print): Glenn D. Wadsworth

Title of Operator: Plant Manager

Signature of Operator: *Glenn D. Wadsworth*

Date: 01/13/99

jb  
a:\forms\MR-AR






**REILLY  
WENDOVER**



WENDOVER, UTAH

EVAPORATION PONDS  
&  
COLLECTION AREA



**LEGEND**

NEW DITCH  
COLLECTION DITCH  
DITCH/LEAK  
TRANSFER DITCH  
POND/LEAK  
PROPOSED PRIMARY POND  
PROPOSED SECONDARY POND  
PROPOSED TERTIARY POND  
POND/LEAK  
UTAH STATE LEAKS  
POND SYSTEM VI



POND SYSTEM VI construction